

The Strongest Connection

Normal Gauge	&	Heavy Gauge
DESCRIPTION	CODE	SIZE
Coupler		
	c12	1/2"
	c34	3/4"
	c1	1"
	c114	1 1/4"
	c112	1 1/2"
	c2	2"
Reducer		
	r3412	3/4" x 1/2"
	r112	1" x 1/2"
	r134	1" x 3/4"
	r11434	1 1/4" x 3/4"
	r1141	1 1/4" x 1"
	r1121	1 1/2" x 1"
	r112114	1 1/2" x 1 1/4"
	r2114	2" x 1 1/4"
	r2112	2" x 1 1/2"
Male BSP Adaptor		
	ma12	1/2"p x 1/2" bsp
	ma3412	3/4"p x 1/2" bsp
	ma34	3/4"p x 3/4" bsp
	ma134	1"p x 3/4" bsp
	ma1	1"p x 1" bsp
	ma114	1 1/4"p x 1 1/4" bsp
	ma112	1 1/2"p x 1 1/2" bsp
Female BSP Adaptor		
	fa12	1/2"p x 1/2" bsp
	fa3412	3/4"p x 1/2" bsp
	fa34	3/4"p x 3/4" bsp
	fa134	1"p x 3/4" bsp
	fa1	1"p x 1" bsp
	fa114	1 1/4"p x 1 1/4" bsp
	fa112	1 1/2"p x 1 1/2" bsp
fa2	2"p x 2" bsp	

Normal Gauge	&	Heavy Gauge
DESCRIPTION	CODE	SIZE
Unequal Tee		
	rt3412	3/4" x 1/2"
	rt112	1" x 1/2"
	rt134	1" x 3/4"
	rt11434	1 1/4" x 3/4"
	rt1141	1 1/4" x 1"
	rt1121	1 1/2" x 1"
	rt112114	1 1/2" x 1 1/4"
90° Bend		
	b12	1/2"
	b34	3/4"
	b1	1"
	b114	1 1/4"
	b112	1 1/2"
	b2	2"
Male 90° BSP Bend		
	mb12	1/2"p x 1/2" bsp
	mb3412	3/4"p x 1/2" bsp
	mb34	3/4"p x 3/4" bsp
	mb341	3/4"p x 1" bsp
	mb134	1"p x 3/4" bsp
	mb1	1"p x 1" bsp
	mb114	1 1/4"p x 1 1/4" bsp
Female 90° BSP Bend		
	fb12	1/2"p x 1/2" bsp
	fb3412	3/4"p x 1/2" bsp
	fb34	3/4"p x 3/4" bsp
	fb1	1"p x 1" bsp
	fb114	1 1/4"p x 1 1/4" bsp
	fb112	1 1/2"p x 1 1/2" bsp
	fb2	2"p x 2" bsp

GRIPMAX HYDRODARE PIPES

NG12	1/2"	150m
NG12x25	1/2"	25m
HG12	1/2"	150m
HG12x25	1/2"	25m
NG34	3/4"	150m
NG34x25	3/4"	25m
HG34	3/4"	150m
HG34x25	3/4"	25m
NG1	1"	150m
HG1	1"	150m
NG114	1 1/4"	150m
NG112	1 1/2"	150m

